

I would like to get approval from the board for Salnor Roofing Services Ltd to carry out work to the Community Centre roof following its annual inspection. We have also had a small leak in the kitchen



The cost of the work is £300.00 + VAT @20%

This company was recommended by Surrey County Council and is the company that has been completing work on the Youth Club roof.

Following inspection:

There is an amount of build up of leaves and debris from the nearby trees piled up between the two levels in the roofs and there is also some bricks and paving slabs on the upper roof that appear to be serving no purpose.

The standing water that can be seen on the lower roof is mainly down to the build-up of debris preventing it from flowing through the rainwater chutes.

As part of annual maintenance this debris should be cleared from the roof areas together with the bricks and paving slabs.





Salnor roofing also believes that two joints in the parapet capping need attention and could be contributing to the leak in the kitchen. The quote includes them resealing these when clearing the debris from the roof.

